


CORNER RECORD

Document Number 8N23-28-3
 City of _____ County of MONO, California

Brief Legal Description PORTION OF SEC 21 & SEC 28, T8N, R23E, MDR&M



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

EVIDENCE FOUND TO REESTABLISH PROPERTY CORNERS: 1/4 COR 329/328-2 1/2" DIA. BR. CAP ON 1" DIA. IRON PIPE, 2' ABOVE GROUND IN 3' DIA ROCK MOUND; SEC. COR. 320/321/328/329-2 1/2" DIA BR. CAP ON 2" DIA IRON PIPE @ AP IN FENCE; 1" I.D. IRON PIPE, TAG MISSING ADJACENT TO POWER POLE

PROPERTY CORNERS REESTABLISHED FROM FOUND MONUMENTS, RECORD OF SURVEY NO. 31-12 & RECORD COORDINATE INFORMATION IN BEAR ENGINEERING FILE. A description of the physical condition of the monument as found and as set or reset: MONUMENTS

OBSCURED PRIOR TO AND/OR DURING JANUARY, 1997 FLOOD OF WEST WALKER RIVER. FOUND 1/4 COR. & PROPERTY CORNER IN GOOD CONDITION. SEC. COR. IS BEAT; HAS BEEN DISTURBED SINCE SURVEY OF 1981.

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MARCH 10 1997.

Signed John R Langford L.S. or R.C.E. Number LS 5149

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 20 1997 and examined and filed APRIL 8 1997.

Signed P. B. BROWN Title MONO COUNTY SURVEYOR
EXP. 9-30-99



County Surveyor's Comment _____

